


















IA600 Calibration Frame
PACKING LIST
Camera Version



<p>Stand</p>		<p>Laser Measurement Unit</p>		<p>Sealing Strip x2</p>	
<p>Upper Crossbar</p>		<p>Storage Bracket x2 (AUTEL-CSC1500/09)</p>		<p>Rubber Pad x2</p>	
<p>Lower Crossbar</p>		<p>Connecting Bar</p>		<p>Allen Key (5 mm)</p>	
<p>Base</p>		<p>Expansion Bolt x4 (M12 x 80)</p>		<p>Expansion Bolt x8 (M6 x 50)</p>	
<p>Large Sliding Plate</p>		<p>Socket Head Cap Screw x4 (M8 x 20)</p>		<p>Washer x2</p>	
<p>Quick Reference Guide</p>		<p>Packing List (This document)</p>	